

WFT FAA Repair Station Process Cross Reference

Process Description	Pratt & Whitney	General Electric	CFMi	IAE V2500	Rolls Royce
Alkaline Rust Remover (Ti Only)	PWA SPOP 18 Task 70-21-00-110-006	GE SPM 70-21-09-110-007	CFM 56 TSK 70-21-14-110-004	70-11-06-300-503	OP 136
Nitric Strip Plasma Coatngs	PWA SPOP 50 TASK 70-44-01-330-019	GE SPM 70-23-12-110-027	CFM 56 TSK 70-23-38-330-024 CFM 56 TSK 70-23-34-330-021	70-33-59-300-503	
4 Step Alk.Clean/ Acid Descale	PWA SPOP 211 TASK 70-21-00-110-008	GE SPM 70-21-20-110-038	CFM 56 TSK 70-21-32-110-008		OP 134
Alkaline Rust Remover	PWA SPOP 203 TASK 70-21-00-110-007	GE SPM 70-21-06-110-004	CFM 56 TSK 70-21-31-110-007	70-11-13-300-503	OP 121
Aqueous Degreasing	PWA SPOP 209 TASK 70-21-00-110-041	GE SPM 70-21-22-110-042	CFM 56 TSK 70-21-18-160-003	70-11-03-300-503	OP 102
Strip Of Chrome Carbide	PWA SPOP 324 TASK 70-44-01-330-900	GE SPM 70-23-16-100-003		70-33-90-300-503	
Ni Plating on SS, Co & Ni Base	PWA SPOP 26 TASK 70-44-01-330-006			70-33-06-300-503	
Application of Corrosion Inhibitor	PWA SPOP 5 TASK 70-21-00-110-048	GE SPM 70-60-00-620-001			OP 340
Dry Abrasive Blast Cleaning	PWA SPOP 218 TASK 70-21-00-120-004	GE SPM 70-47-03-380-018	CFM 56 TSK 70-51-11-120-012 CFM 56 TSK 70-51-11-120-002	70-12-02-120-501 70-12-09-120-501	
Descaling Martensitic Alloys			CFM 56 TSK 70-21-32-110-008		
Strip Tungsten Carbide	PWA SPOP 317 TASK 70-44-01-330-043	GE SPM 70-23-09-110-022 GE SPM 70-23-09-100-002	CFM 56 TSK 70-23-40-110-027		
Masking-General	PWA SPOP 36 TASK 70-44-01-330-008		CFM 56 TSK 70-15-00-330-001		
4 Step Alk.Clean/ Acid Descale	PWA SPOP 213 TASK 70-21-00-110-009	GE SPM 70-21-10-110-008	CFM 56 TSK 70-21-41-110-011	70-11-54-300-503	OP 134
Chromium Plating	PWA SPOP 22 TASK 70-44-01-330-002		AMS 2406 Chromium, Hard CFM 56 TSK 70-61-14-330-028	70-33-02-300-503	
Nickel Plating on Steel (not SS)	PWA SPOP 29 TASK 70-44-01-330-007			70-33-05-300-503	
Stripping TBC Bond Coat	PWA SPOP 319 TASK 70-44-01-330-045			70-33-77-300-503	

